

FIELD INSPECTION REPORT

Date of Inspection : 02.12.20		District: Gaya	
Division : Gaya		Length (km): 1.650 K.M.	
Name of the Road: Nagwan Road to Bajda			
Scheme/Programme:		MAINTENANCE New Maintenance Policy 2018	
Package No.: MR-N/19-20/Gaya/09		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance Completed	
Work is a case of:		New Connectivity/Up gradation/ Maintenance Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	