

# FIELD INSPECTION REPORT


Date of Inspection :	02.12.2020.	District:	Gaya.
Division :	Gaya.	Length (km):	0.62 km.
Name of the Road:	Gaya Petchpur road to Shaifpur		
Scheme/Programme:	MAINTENANCE	New Maintenance Policy 2018.	
Package No.:	MR-N/19-20/Gaya/07.	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		Completed.
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A.
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Harishankar  
NAME:

(Signature)   
02.12.20