

FIELD INSPECTION REPORT

Date of Inspection : 02.12.20		District: Gaya	
Division : Gaya		Length (km):	
Name of the Road: Meyari Road to Sultanpur Karma			
Scheme/Programme:		MAINTENANCE MR-N/19-20/Gaya/09	
Package No.: MR-N/19-20/Gaya/09		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance Completed	
Work is a case of:		New Connectivity/Up gradation/ Maintenance Maintenance.	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Harishankar

NAME:


 (Signature)
 J. E.