

FIELD INSPECTION REPORT

Date of Inspection : 03.12.20	District: Gaya
Division : Gaya	Length (km): 2.50 K.M.
Name of the Road: Patchpur Rajauli Road to Kanti	
Scheme/Programme:	MAINTENANCE New Maintenance Policy 2018
Package No.: MR-N/19-20/Gaya/09	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance Completed
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Harishanka

NAME:


 03.12.20
 (Signature)



Scanned with
CamScanner