## FIELD INSPECTION REPORT

Date of Inspection: 02º 12. 2020			District: GAYA  Length (km): 3.635 KM	
	1: SHERGH			
		T. ROAD ROHL MAINTENANCE	TO BHAGHAR MR	
	/Programme:	10 - 01 1 1/14	Road Id No.:	
Status o	of the Project:	19-20 Shorghet /14	/Under Maintenance ONGOIT	19
	s a case of:	New Connectivity/L	Jp gradation/ Maintenance	fi was don
Sl. No.	10 9 90 000	Parameters to	be checked	Remarks
	No. of the last			S/U
1.		Pavement		
a)		Road Junction condition		
b)	Condition of S	Condition of Surfacing		₹/U
c)	Riding Quality	Riding Quality		\S/U
d)	Road Camber	Poad Camber		
e)	Whether free from defects such as visible cracks, exposed Yes/No			
۷)	aggregates in case of CC Pavement.  Yes/No  Yes/No			
f)	Contraction Joints provided or not (CC Pavement)  Yes/No  Yes/No			Yes/No
g)	Compaction of flank/slope & raincuts if any			1000 ac. 1000
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRI/U NOT DON
b)	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/U			S/SRI/U
	Condition of railings/slab/approach for Bridges  S/SRI/U			S/SRI/U
c)	Road Furniture			
3.			Latinary Board from & 200m	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

(Signature) 16.