## FIELD INSPECTION REPORT

Date of	Inspection: O	2.12.2020 District: Patua	· · · · · · · · · · · · · · · · · · ·
Division		Length (km): \. C.O.O.	
Name of	the Road:	Tuzarchak (Usari Bandh) to sife	indelbus
Scheme	Programme:	MAINTENANCE	12
Package No.: MR-N 19-20-Danahay 08 Road Id No.:			
Status of the Project: Ongoing/Completed/Under Maintenance			
o federal banks	a case of:	New Connectivity/Up gradation/ Maintenance	•
Sl. No.		Parameters to be checked	Remarks
i.	Pavement :	Control of the contro	
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of he	S/SRI/U	
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3,	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No-
	Compliance History		
a)	Status of ATR's & any others		
Overall I	Rating •	Work not Stalted	
J. Oluli I		Satisfactory (S)	S
		Satisfactory but requires Improvement (SRI)	

(Signature)

NAME: chatubbhy Mandel DESIGNATION: J.E.

Unsatisfactory (U)