

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Nawada
Division :	Nawada	Length (km):	4.00 km
Name of the Road:	Beldar Pakki Road to Mohidinpur Road.		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20 Nawada/12	Road Id No.:	10502601004
Status of the Project:	☒ Ongoing/Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No
4.	Compliance History	
a)	Status of A/R's & any others	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature)

NAME:

FIELD INSPECTION REPORT

Date of Inspection	02/12/2020	District:	Nawada
Division :	Nawada	Length (km):	4.30 km
Name of the Road:	Khedika to Madhukhary		
Scheme/Programme:	MAINTENANCE		
Package No.: MR-N/19-20 Nawada/12	Road Id No.: 10502602076		
Status of the Project :	Designing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.	
D	Contractor joints provided or not (CC Pavement)	Yes/No N.A.	
g)	Compression of bank/slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/ Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History	—	
a)	Status of A.F.R.'s & any others	—	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

NAME:


 02.12.2020
 (Signature)
 E. E. Nawada