


FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Maheula
Division : Maheula	Length (km): 2.3
Name of the Road: Jambhaja Road to Parana Road	
Scheme/Programme: MAINTENANCE (3054)	
Package No.: MR(3054)	Road Id No.: 10502602059
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 (Signature)
 ACP Maheula

NAME: