

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		District: Patna
Division : Danapur		Length (km): 2.400
Name of the Road: Mathiyapur to Ashapur Lakhni Bigha Road		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	-S/UV ✓
c)	Riding Quality	-S/UV ✓
d)	Road Camber	-S/UV ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. B.T. Road	Yes/No
f)	Contraction Joints provided or not (CC Pavement) B.T. Road.	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: Chaturbhuj Mandal

DESIGNATION: J.E.

(Signature) 02/12/20