## FIELD INSPECTION REPORT

Date of	Inspection: &	2/12/20 District: Patres	<del></del>
Division	n: Dang	Length (km): 2.40 K	M.
Name o	f the Road:	Usare Rewa to Sarae Chiptan	Pont -
Scheme/Programme:		MAINTENANCE	Sector 10
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
SI. No.		Parameters to be checked	Remarks
	Payement		
a)	Road Junction	condition	, 8/4
b)	Condition of S	urfacing	-8/U_\
c)	Riding Quality 8		
d)	Road Camber	&/U √	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement) Yes/No		
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainag		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/U		
c)	Condition of railings/slab/approach for Bridges S/SR		
3.	Road Furnitur	<b>e</b>	
a)		boards/informatory/cautionary Board/km & 200m at road markings are provided and maintained	Yes/No~
A. A.	Compliance it	story.	
a)	Status of ATR's	s & any others	en en en en en partir plant de

Overall Rating

Satisfactory (S)	,
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	J.

(Signature)

NAME:

Denesh charellany

DESIGNATION:

A.E