2

FIELD INSPECTION REPORT

		TNA	
Division	JANATOR Length (km):	1.8	
Name of	the Road: NH-30 Deckuli to Doghoa Air		ete Raad
Scheme/Programme: MAINTENANCE Package No.: Road Id No.:			
	f the Project: Ongoing/Completed/Under Maintenance	The state of the s	
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
	Pavement		2.54.
a)	Road Junction condition		Æ /U
b)	Condition of Surfacing		,8/U
c)	Riding Quality		,87U
d)	Road Camber	100	% ÎU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No_
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including i	its painting	S/SRI/U
b) '	Condition of Abutment & Wing walls, Slab in RCC culve	rts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km stones/Pavement road markings are provided and maintain		Xes/No
4.	Compliance History		
a)	Status of ATR's & any others	A STATE OF THE PARTY OF THE PAR	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

J.E. Bilde

02/12/20

(Signature)

NAME:

Anil Kumax

DESIGNATION: J.E, Bihta