

out of Maintenance period

Block:- pirpainti

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Bhagalpur
Division :	Kathalgaon	Length (km):	2.30 km
Name of the Road:	Meharpur to Dadar		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	20703408027
Status of the Project:	Ongoing/Completed/Under Maintenance <u>out of Maintenance</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>Maintenance</u>		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		NA
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	No.
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Not Applicable

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	

This road is out of Maintenance period.
Actual completion date:- 21/03/2014.

AE
02/12/2020

Signature
21/12/2020

NAME: