

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: BANKA
Division : Banka-2	Length (km):
Name of the Road: BWP-DUMKA ROAD (SANTHYATRI) - SUKHAIBABARAIT	
Scheme/Programme:	MAINTENANCE
Package No.: RM/BA/BAN/20/004	Road Id No.: 20703502048
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	satisfactory. (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pritam
02.12.2020
(Signature)

NAME: PRITAM KUMAR

DESIGNATION: A.E