

# FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020	District: Banka
Division : BANKA-2	Length (km): 5.133
Name of the Road: Bhagalpur Dumka Road to Bhawanipur	
Scheme/Programme: MAINTENANCE	MR (3054)
Package No.: RM/BA/BAN/19/0008	Road Id No.: 20703502049
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U on going
b)	Condition of Surfacing	S/U on going
c)	Riding Quality	S/U on going
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U on going
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U on going
c)	Condition of railings/slab/approach for Bridges	S/SRI/U on going
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No on going
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Aj  
02.12.2020  
(Signature)

NAME: Ajay Kumar

DESIGNATION: AE