

# FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: East Arunachal Pradesh
Division : Aizawl	Length (km): 1.05
Name of the Road: Phalanang PWD Road b/h. Yajitkappa Pipri Saboraisa Part 6	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 31723/03213
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	No Yes/No
	<b>Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Maintenance done not reflected Yes Yes/No SRI
	<b>Compliance History</b>	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

*(Signature)*  
2/12/2020

NAME: Ashok Kumar

DESIGNATION: JE/RWD  
Aizawl