

FIELD INSPECTION REPORT

Date of Inspection:-03.12.2020		District:- Sitamarhi.
Division:-RWD, Works Div. Pupri.		Length (km):-4.5
Name of the Road:- Majhaur to Lohaitha in Nanpur Block.		
Scheme/Programme:-		MAINTENANCE
Package No.:- MR-N/2019-20 Pupri/01		Road Id No.: NEA22 0001910
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railing/slab/approach for bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/Km & 200m stones/Pavement road marking are provided and maintained	✓Yes/No
4.	Compliance History	N/A
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:- RAMBABU & Praveen Kr. Pandey

(Signature)

DESIGNATION:- E-E, RWD, WORK DIVISION
PUPRI & JE

03.12.20
JE