

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	East Champaran
Division :	WORKS DIVN DHAKA	Length (km):	7.10 km
Name of the Road:	Mozihari Dhaka PWD road to Pakari Kapoor		
Scheme/Programme:	MAINTENANCE (New Maintenance Policy 2018)		
Package No.:		Road Id No.:	NEA22000192
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ramchandra Paswan
DESIGNATION: Executive Engineer

02/12/2020
Executive Engineer
(Signature)
R. W. D. Works Division
Dhaka
02/12/20
J.E