

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: Kaimur
Division : Mohania	Length (km): 7.95 km
Name of the Road: Baddha To Akourse	
Scheme/Programme: MAINTENANCE	MR - 2018
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Ongoing
Work is a case of: New Connectivity/Up gradation/ Maintenance	Upgradation.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No ongoing
g)	Compaction of flank/slope & raincuts if any	Yes/No ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No Yes. Main board to be replaced.
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work is a case of ongoing.

NAME: Md. Jamil Abul Hassam

(Signature)

AE

02/12/2020