

# FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020		District: Muzaffarpur
Division : R.W.D. Muzaffarpur		Length (km): 2.65 Km
Name of the Road: Mungeli Petrol Pump - Chhatra via Bidha		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

  

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	15
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: KUNIL KUMAR

DESIGNATION: J/E

  
 (Signature) 2/12/2020