

FIELD INSPECTION REPORT

Date of Inspection : 3/12/20
 Division : Muradpur Gern-1
 Name of the Road: Basantpur Chowk to Basaitia village
 District: Muradpur
 Length (km): 2.08 km
 Scheme/Programme: MAINTENANCE
 Road Id No.:
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S SU
b)	Condition of Surfacing	S SU
c)	Riding Quality	S SU
d)	Road Camber	S SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI/U
c)	Condition of railings/slab/approach for Bridges	SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

[Signature]
3/12/20