FIELD INSPECTION REPORT

Da	to oto Iurbection: 8/13/3030	District : GAYA		
Div	ison: Neemchak Bathani	Length (Km.: 2.50	7	
Sch	eme/Programme:	MAINTENANCE (RAIght WAZINGAM) Road to	Basas)	
Package No. ;		HR-H12013-20 Hrachak Bathani 104 Road Id No.:		
Status of the Project :		Ongoing/Completed/Under Maintenance	Completed/Under Maintenance	
Voi	rk is a case of;	New Connectivity/Up gradation/Maintenance		
SI.		Parameters to be checked	Remarks	
1	Pavement		Is/U	
a)	Road Junction condition			
b)	Condition of Surfacing			
c)	Riding Quality			
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No Yes/No	
n	Contraction Joints provided or not (CC Pavement)		Yes/No	
	Compaction of flank/slope & raincuts if any			
2	Cross Drainage	in 2	S/SRI/U	
)	Condition of head walls in Hume pipe culverts including its painting			
)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/L	
	Condition of railings/slab/approach for Bridges			
1	Road Furniture	Paced from & 200m stones/Pavement road markings are provide	ed Yes/No	
)	Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided Yes/No and maintained			
_	Compliance History			
10	status of ATR's & any others.			

Overall Rating

	1 1
Satisfactory (S)	347
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note: - work has been not started.

VUTAY KUHAR PANDEY ASSISTANT ENGINEER RWD. H. BATHANI 3/12/2020 AE