

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020		District : GAYA	
Division : Neemchak Bathani		Length (Km. : 2.50 Km.	
Scheme/Programme:		MAINTENANCE (Jethan Ghatt Jammuan Road - Chegra	
Package No. :		MR-N/2019-20	Road Id No. :
Status of the Project :		Neemchak Bathani Job Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Parameters to be checked			Remarks
Sl. No.			
1	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4	Compliance History		
a)	Status of ATR's & any others.		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE - work has been not started.

VIJAY KUMAR PANDEY
ASSISTANT ENGINEER
RWD N. BATHANI


3/12/2020
AE