

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Munger
Division :	Munger	Length (km):	9.00
Name of the Road:	Murkatta Atthan to Bangalwa via - Mahgama, kather		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Y/N/A
f)	Contraction Joints provided or not (CC Pavement)	Y/N/A
g)	Compaction of flank/slope & raincuts if any	Y/N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/N/A
c)	Condition of railings/slab/approach for Bridges	S/N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	work is in starting position. materials has been dumped by contractor.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Balmiki Prasad Bisha.
NAME:


(Signature) AE