

FIELD INSPECTION REPORT

Date of Inspection :- 2.12.2020 District :- Nalanda.
 Division :- Rajgir. Length (km) :- 2.850 k.m
 Name of the Road :- SH-71 Kathisarai More to Kadiridih via Bhagwampur.
 Scheme/Programme: MAINTENANCE (3054 MR) New Maintenance Policy-2018.
 Package No.: - RM/NA/RAJ/. Road Id No.: - 1291010278.
 Status of the Project: Ongoing Completed Under Maintenance Ongoing.
 Work is a case of: New Connectivity Up gradation Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA)
g)	Compaction of flank slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No (Rest yet to be done).
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S


 2.12.20
 (Signature)

NAME:- Kishor Kumar
 Assistant Engineer
 Kathisarai.