

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020	District: Nalanda
Division : Rajgir	Length (km): 1.8 km
Name of the Road: Dhunikiya Baba mandir se chekpar	
Scheme/Programme: MAINTENANCE (3054 MR)	
Package No.: Batch RM/NA/RAJ/20/0001	Road Id No.: 1291010279
Status of the Project: Ongoing (Completed Under Maintenance)	Ongoing
Work is a case of: New Connectivity Up gradation Maintenance	Up Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA) ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA) ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (NA) ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (NA) ✓
c)	Condition of railings slab approach for Bridges	S/SRI/U (NA) ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No (Work in progress) ✓
4.	Compliance History	
a)	Status of ATR's & any others	No


Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S


3.12.20
(Signature)

NAME: - Kishor Kumar
Assistant Engineer
Rajgir.