

FIELD INSPECTION REPORT

Date of Inspection :- 2.12.2020 District :- Nalanda.
 Division :- Rajgir. Length (km) :- 0.950 K.M
 Name of the Road :- Kasturba Lohrajpur path se Gangaapur Palashpur
 Scheme/Programme: MAINTENANCE (3054 MR) Middle School Tak.
 Package No.: - RM/NA/RMJ/2019/001. Road Id No.: - 1291010280.
 Status of the Project: Ongoing Completed/Under Maintenance Ongoing.
 Work is a case of: New Connectivity Up gradation/ Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (N.A)
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S SRI/U
c)	Condition of railings/slab approach for Bridges	✓ S SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No (Rest yet to be done).
4.	Compliance History	
a)	Status of ATR's & any others	No


Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S


 2.12.20
 (Signature)

NAME :- Kishor Kumar
 Assistant Engineer
 Kabisarai.