

FIELD INSPECTION REPORT

Date of Inspection: 02/11/20 District: Nalanda.
 Division: Patna Length (km): 1.100km.
 Name of the Road: Silao - Patna Mulehya Marg to Mahuri Bazar Bule.
 Scheme/Programme: MAINTENANCE 8054 MR New-M 2018.
 Package No.: RM 12/19/0005 Road Id No.: 1291010307.
 Status of the Project: Ongoing Completed Under Maintenance Not started.
 Work is a case of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S U
b)	Condition of Surfacing	S U
c)	Riding Quality	S U
d)	Road Camber	S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No
f)	Contraction Joints provided or not (CC Pavement)	Yes No
g)	Compaction of flank slope & raincuts if any	Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SR U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SR U
c)	Condition of railings slab approach for Bridges	S SR U
3.	Road Furniture	
a)	Whether sign boards-informatory cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes No
4.	Compliance History	
a)	Status of A/R's & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SR)

Unsatisfactory (U)

Sandeep Kumar

NAME:

W/O 2/11/20
(Signature) *DF*