

FIELD INSPECTION REPORT

Date of Inspection :	02/11/20	District:	Nalanda.
Division :	Patna	Length (km):	1.500km.
Name of the Road:	B.Ed college Kuthiama more to Juaforidh.		
Scheme/Programme:	MAINTENANCE	3054 MR New. M-2018	
Package No.:	RM/NA/RAJ/19/0004	Road Id No.:	1291010308.
Status of the Project:	Ongoing Completed/Under Maintenance <u>ongoing.</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>Maintenance.</u>		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

✓ S

Sakunt Kumar.

NAME:

(Signature) 01/11/20