

ONLY POT PATCH DONE

FIELD INSPECTION REPORT

Date of Inspection:	2-12-2020	District:	NALANDA
Division:	HARNAUT	Length (km):	5.000
Name of the Road:	Nagarnaula chero pass path ke neapali to sindura villages via chhiddi, Nagapur, Siraupur		
Scheme/Programme:	MAINTENANCE		
Package No.	MR-N/19-Harnaut/01	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a category of:	New Connectivity/Up gradation/ Maintenance		


Sl. No.	Parameters to be checked	Remarks
1.		
a)	Condition condition	S/U
b)	Condition of Surfacing	S/U
c)	Quality	S/U
d)	Condition	S/U
e)	Free from defects such as visible cracks, exposed in case of CC Pavement.	Yes/No
f)	Joints provided or not (CC Pavement)	Yes/No
g)	Condition of flank/slope & raincuts if any	Yes/No
2.		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.		
a)	Design boards/informatory/cautionary Board/km & road markings are provided and maintained	200m Yes/No
4.		
a)	Other's & any others	

Overall

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)



(Signature)

NAME: MUKESH KUMAR SINHA