


FIELD INSPECTION REPORT

only pot patch done

Date of Inspection:	2-12-2020	District:	NALANDA
Division:	HARNAUT	Length (km):	
Name of the Road:	Harnaut Salkowra NH-30A Road to Langhaura village via Miridabachak.		
Scheme/Project Name:	MAINTENANCE		
Package No.:	MR-N/19-Harnaut/01	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is for:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Function condition		S/U
b)	Condition of Surfacing		S/U
c)	Quality		S/U
d)	Thickness		S/U
e)	Free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Expansion Joints provided or not (CC Pavement)		Yes/No
g)	Condition of flank/slope & raincuts if any		Yes/No
2.	Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Signage		
a)	Design boards/informatory/cautionary Board/km & pavement road markings are provided and maintained	200m	Yes/No
4.	Accident History		
a)	Accidents & any others		

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: MUKESH KUMAR Salkowra