## FIELD INSPECTION REPORT

District: East Champaran Length (km): 1.660 KM 02/12/20 Date of Inspection: Division: Raxall Name of the Road: Andhra REO Road to Harkatha MAINTENANCE Scheme/Programme: Package No.: RM/EA/RAX/19/0002 Road Id No.: 317851031888 Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of:

Work	is a case of: New Connectivity/Off gradations Transfer			
SI. No	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition	28/0		
b)	Condition of Surfacing	<b>18/</b> U		
c)	Riding Quality	<b>~8</b> /U		
d)	Road Camber	<b>\27</b> U		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Jes/No N		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No		
g)	Compaction of flank/slope & raincuts if any	Yes/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	VS/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/UNA		
c)	Condition of railings/slab/approach for Bridges	S/SRI/UNA		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Ycs/No		
1.	Compliance History			
)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	ı	_	1
Satisfactory but requires Improvement (SRI)		2	
Unsatisfactory (U)			<del></del> .

NAME: SHASHI KANT SINGH DESIGNATION: JUNIOR Engineer