

FIELD INSPECTION REPORT

Date of Inspection : 3/12/20	District: East Champaran
Division : Raxaul.	Length (km): 2.81 km
Name of the Road: GBC chainia chawki to chitthabati	
Scheme/Programme:	MAINTENANCE
Package No.: RM/EA/RAX/19/0002	Road Id No.: 317851031949
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Upgradation/ Maintenance

Sl.No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


3/12/20
(Signature)

NAME: Shashi Kant Singh

DESIGNATION: Junior Engineer