

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020		District: Katihar.	
Division : Katihar		Length (KM) : 5.80 KM	
Name of Road:		Kozha NH-31 Burga Sthan To Baura	
Scheme/ Programme:		MAINTENANCE	
Package No. MR-N/19-20		Katihar/10 Road ID No. 2115510 31957	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition		S/U NA
b)	Condition of Surfacing		S/U NA
c)	Riding Quality		S/U NA
d)	Road Camber		S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)		Yes/No NA
g)	Compaction of flank/slope & raincuts if any		~Yes/No partly
2	Cross Drainage		
a)	Condition of headwalls in Humepipe culverts including its painting		S/SRI/U NA
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U NA
c)	Condition of railings/slabs/approach for Bridges		S/SRI/U NA
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		~Yes/No partly
4	Compliance History		
a)	Status of ATR & any others		No
Overall Grading:		Satisfactory (S)	S
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: Vijay Kumar
Designation: A.E. Katihar

3.12.2020
(Signature)

R.W.D. Works Div., Katihar