

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: East Champaran
Division : Rayaul	Length (km): 3.68 Km	
Name of the Road: PWD Road Talouppur to Masadi		
Scheme/Programme: MAINTENANCE		
Package No.: 7	Road Id No.: 317851032015	
Status of the Project: Opening complete/Under Maintenance		
Work is a case of: New Connectivity/UP gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SRI N.A.
b)	Condition of Surfacing	SRI
c)	Riding Quality	SRI
d)	Road Camber	SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of Flank/slope & raincuts if any	Yes/No Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/NI N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/NI N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/NI N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A.
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Shyam Sundar Jais
DESIGNATION: A.E. Works and M.V. Chauradono


(Signature)
03/12/2020