

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Jammu
Division :	Jammu	Length (km):	3.940 KM
Name of the Road:	Jammu-Pin Road to Abhaypur		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20/Jammu/12	Road Id No.:	28411032558
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	N.A	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

(Signature)

Executive Engineer
R.D. (N) DIVISION
JAMMU