

FIELD INSPECTION REPORT

(Potter - Jagdishpur)

Date of Inspection: 03/12/2020		District: Bhagalpur	
Division: Bhagalpur		Length (Km): 1.20 Km.	
Name of the Road: Dat Bah Gramin Cold Storage to Takkipur via - Salepur Road			
Scheme/Programme: MAINTENANCE			
Package No.: Group No - 12		Road Id No.: 2732-1032-660	
Status of the Project: Ongoing / completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating : Work in Progress.

Satisfactory(S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	—

Signature
31/12/20
J.E.

Signature
03/12/20
A.R.

NAME: Radho Raman Singh

DESIGNATION: (Assistant Engineer)