


(5)
FIELD INSPECTION REPORT

Date of Inspection :	2/12/2020	District:	Nawadga.
Division :	Rajauli	Length (km):	3.0 KM
Name of the Road:	NH 31 to Garibas		
Scheme/Programme:	MAINTENANCE		
Package No.:	MRN/19-20 Rajauli/116	Road Id No.:	15271032258A1
Status of the Project:	Ongoing/Completed/Under Maintenance :- Ongoing		
Work is a case of:	New Connectivity/Up gradation/ Maintenance :- Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - N/A
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No problem of C.C.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No Yet to be done.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ?
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No } Yet to be done
4.	Compliance History	
a)	Status of ATR's & any others	- NIL

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 (Signature) 2/12/20

NAME: MANOJ KUMAR

DESIGNATION: Executive Engineer