

Not started

Block:- piprainti

FIELD INSPECTION REPORT

Date of Inspection : <u>03/12/2020</u>	District: <u>Bhagalpur</u>
Division : <u>Katangaon</u>	Length (km): <u>2.0 Km</u>
Name of the Road: <u>NH 80 to Harinkol paharya to 6 via Thamar</u>	
Scheme/Programme: <u>MAINTENANCE</u>	<u>New Maintenance policy</u>
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Ongoing</u>
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>Maintenance</u>

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	<u>S/U</u>	<u>NA</u>
b)	Condition of Surfacing	<u>S/U</u>	<u>NA</u>
c)	Riding Quality	<u>S/U</u>	<u>NA</u>
d)	Road Camber	<u>S/U</u>	<u>NA</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<u>Yes/No</u>	<u>NA</u>
f)	Contraction Joints provided or not (CC Pavement)	<u>Yes/No</u>	<u>NA</u>
g)	Compaction of flank/slope & raincuts if any	<u>Yes/No</u>	<u>NA</u>
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	<u>S/SRI/U</u>	<u>NA</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>S/SRI/U</u>	<u>NA</u>
c)	Condition of railings/slab/approach for Bridges	<u>S/SRI/U</u>	<u>NA</u>
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>Yes/No</u>	<u>NO</u>
4.	Compliance History		
a)	Status of ATR's & any others	<u>NO</u>	

Overall Rating :

Work yet to be started.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	<u>NA</u>


03/12/2020
 (Signature)
BE

NAME: