FIELD INSPECTION REPORT

Date of Inspection: Order					
Division: Bidar & Lord District: Malandar. Name of the Rond Length (km): 0.00 km.					
Name of the Road: Length (km): 0.90 k.M.					
Scheme/Programme: Jacob Scheme/Programme: Jacob Road to Akharpur					
LACKAGE	No.:	MAINTENANCE			
Status of the Project: Ongoing/Completed/Under Maintenance					
Work is a second conditional c					
Sl. No.	The state of the s				
1.	Parameters to be checked			Remarks	
	Pavement				
n)	Road Junction condition			S/U (
b)	Condition of Surfacing			S/U	gardinates The second
c)	Riding Quality			S/U	
q)	Road Camber			S/U	11
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No]\
· 1)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				Work Not
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	J TSTaste a.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				1.0
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
響響	Compliance History			1	~ ~
a)	Status of ATR	's & any others			

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NA

NAME: Mukely Eddars

DESIGNATION: J.E.

Scanned with CamScanner

(Signature)