FIELD INSPECTION REPORT

ate of In	spection: 0	21			
Division: Bharsharit			District: Natanda		
Name of the Rond: Kurnhari- Sarbahd			Length (km): 0.450		
cheme/l'	rogramme:	MAINTENANCE	1 Road to Malowan		
'ackage l	Yo.:	MANAGE	Road Id No.:		
Status of the Project: Ongoing/Completed					
			p gradation/ Maintenance		
Sl. No.	Parameters to be		be checked	Remarks	
1.	Pavement				
a)	Road Junction	S/U	S		
b)	Condition of Surfacing			S/U	2
c)	Riding Quality			S/U	5
d)	Road Camber			S/U	5
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				NA
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	NIB
g)	Compaction of flank/slope & raincuts if any			Yes/No	bedon
2.2	Cross Drainage				
a)	Condition of	S/SRI/U	NIA		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	NIA
c)	Condition of railings/slah/approach for Bridges			S/SRI/U	NIO
· 3. · .	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
营4.6	Compliance History				
a)	Status of ATR's & any others				

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) (Signature)

NAME: Mukesh Vadas

DESIGNATION: F.E.