

# FIELD INSPECTION REPORT

Date of Inspection: 2/12/2020		District: Katihar.		Division - Katihar Length 1.890	
Name of Road:		Kursela power house to Majdiya village Kali Sthan			
Scheme/ Programme:		MAINTENANCE			
Package No. M.R.N/19-20/Katihar/10		Road ID No. 211551033033			
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance			
Sl.No	Parameters to be Checked			Remarks	
1	Pavement				
a)	Road Junction Condition			S/U NA	
b)	Condition of Surfacing			S/U NA	
c)	Riding Quality			S/U NA	
d)	Road Camber			S/U NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA	
g)	Compaction of flank/slope & raincuts if any			Yes/No partly	
2	Cross Drainage				
a)	Condition of headwalls in Humepipe culverts including its painting			S/SRI/U NA	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts			S/SRI/U NA	
c)	Condition of railings/slabs/approach for Bridges			S/SRI/U NA	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			Yes/No partly	
4	Compliance History				
a)	Status of ATR & any others			No	
Overall Grading:		Satisfactory (S)		S	
		Satisfactory but requires Improvement (SRI)			
		Unsatisfactory (U)			

Name: CHANDRAHAS KUMAR  
 Designation-  
 Executive Engineer,  
 R.W.D. Works Div., Katihar

(Signature) 