

FIELD INSPECTION REPORT

Date of Inspection: 2/12/2020		District: Katihar.
Division : Katihar		Length (KM) : 2.40 KM
Name of Road:	NH-31 patrol pump To Basgarha via Akama primary School	
Scheme/ Programme:	MAINTENANCE	
Package No. MR-N/19-20 Katihar/10	Road ID No. 211551033037	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No partly
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slabs/approach for Bridges	S/SRI/U NA
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	Yes/No partly
4	Compliance History	
a)	Status of ATR & any others	No
Overall Grading:		
Satisfactory (S)		S
Satisfactory but requires Improvement(SRI)		
Unsatisfactory (U)		

Name: Dilip Kumar
Designation- J.E

(Signature)
2/12/2020

R.W.D. Works Div., Katihar