

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020	District: Namada	
Division : Rajanli	Length (km): 1.73	
Name of the Road: KENDUA to MADHORAMPUR		
Scheme/Programme:	MAINTENANCE	
Package No.: MR-N/19-20 Rajanli/12	Road Id No.: 1527103304	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>Maintenance</i>	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <i>NA</i>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <i>NA</i>
g)	Compaction of flank/slope & mircuts if any.	Yes/No ✓
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <i>work at to be done</i>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <i>NA</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <i>work at to be done</i>
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Shub
2/12/20
(Signature)

NAME: *Sumit Kumar*

DESIGNATION: *Assistant Engineer*