

FIELD INSPECTION REPORT

Date of Inspection : 02/11/20 District: Nalanda.
 Division : Rajgir. Length (km): 1.600km
 Name of the Road: Bargam Kaikaila Path to Barshali via Pachor
 Scheme/Programme: MAINTENANCE 3054 MR NEW M-2018.
 Package No.: RM/NAIRAJ/19/0004 Road Id No.: 1291033058.
 Status of the Project: Ongoing ☒ Completed ☐ Under Maintenance ☐ ongoing
 Work is a case of: New Connectivity ☐ Up gradation ☐ Maintenance ☒ Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	Work in progress
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Bedding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	Work in progress
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab approach for Bridges	S/SR/U
3.	Road Furniture	Work in progress
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO.

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SR)

Unsatisfactory (U)

Satish Kumar

NAME:


 (Signature) 2/11/20