

# FIELD INSPECTION REPORT

(Block - Jagdishpur)

Date of Inspection: 03/12/2020 | District: Bhagalpur.  
 Division: Bhagalpur. | Length (Km): 2.70 Km.  
 Name of the Road: Bhagalpur - Baimar RD Road (Bajani More) to Samnagar Hanjuntola.  
 Scheme/Programme: MAINTENANCE  
 Package No.: Group No. 12 | Road Id No.: 2732-1033244.  
 Status of the Project: Ongoing/completed/Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

SL. No.	Parameters to be checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cmpaction of flank/slope & raincuts if any	Yes/No
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
<b>3</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
<b>4</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

NA

NA

NA

NO

Overall Rating: Work In Progress.

Satisfactory(S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	—

31/12/20  
J.E.

03/12/20  
(Signature) RZ

Radhe Raman Singh

NAME: