

# FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020 | District: Bhagalpur

Division: Bhagalpur | Length (Km): 1.810 Km.

Name of the Road: Baunsi RED Road Khirband to Mukheniya Pokhar Road

Scheme/Programme: MAINTENANCE

Package No.: Group NO. 12 | Road Id No.: 27321033247

Status of the Project: Ongoing / completed / Under Maintenance

Work is a case of: New Connectivity / Up gradation / Maintenance

SL. No.	Parameters to be checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating: Work has not been started yet.

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	-

3/12/20  
J.E.

03/12/20  
(Signature) AR

NAME:

Radhe Raman Singh

DESIGNATION:

Assistant Engineer