

FIELD INSPECTION REPORT

(Block - Shahkand)

Date of Inspection :	03/12/2020	District : Bhagalpur
Division : Bhagalpur	Length (Km) :	2.40 km
Name of the Road :	Shivshankar PWD Path to Chandari Chauk via Damodar	
Scheme / Programme :	MAINTENANCE	
Package No. / Group no. - 8	Road Id No. :	20703201036
Status of the Project :	Ongoing / Completed / Under Maintenance	
Work is a case of :	New Connectivity / Up gradation / Maintenance	
SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall Rating :	Work has not been started yet.	
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	NA

NAME: Neeraj Kumar

DESIGNATION: JE

03/12/20
(Signature)