

FIELD INSPECTION REPORT

Date of Inspection :	2/12/2020	District:	Nalanda
Division :	Rajgir	Length (km):	0.600 km
Name of the Road:	Bihar Rajgir (NH-82) to Thalar Village		
Scheme/Programme:	MAINTENANCE	(3054 mR)	
Package No.:	Batch RM/NA/RAJ/20/0004	Road Id No.:	1291033631
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA)
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (NA)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (NA)
c)	Condition of railings/slab approach for Bridges	S/SRI/U (NA)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No (work in progress)
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


2.12.20
(Signature)

NAME: - Kishor Kumar
Asst. Sd. Engineer
Rajgir