

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Jamui	
Division : R.W.D. W-Div. Jhajha		Length (km): 2.150 km.	
Name of the Road: Botha To Banderamara Road.			
Scheme/Programme: MAINTENANCE		NEW MIR	
Package No.: RM/JA/JHA/30/0016		Road Id No.: 28421033759	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	N/A
b)	Condition of Surfacing	S/U	N/A
c)	Riding Quality	S/U	N/A
d)	Road Camber	S/U	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	'S'	Work in Progress
Satisfactory but requires Improvement (SRI)		-
Unsatisfactory (U)		-

dui
03/12/2020
(Signature)

NAME: Ranjanam Prasad Singh
DESIGNATION: Junior Engrg.