

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020	District: Nalanda
Division :	Length (km): 2.310 km
Name of the Road: Ben Barwalpur Path se koshnara mote Eksara more Eksara High School	
Scheme/Programme: MAINTENANCE (3054 MR)	
Package No.: Batch RM/NA/RAJ/20/0002	Road Id No.: 1291033841
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance ☒ NOTE started	
Work is a case of:	☒ New Connectivity ☐ Up gradation ☒ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S I
b)	Condition of Surfacing	S I
c)	Riding Quality	S I
d)	Road Camber	S I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SR I
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SR I
c)	Condition of railings slab approach for Bridges	S SR I
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


3/12/20
(Signature)

Rampreet Singh Kumar
NAME: